

Report ID: 26,076,338 3 Version: 16 May 2025 Created:

Make:	LDV	Model:	T60	Body Style:	Utility		Pass	Fail	N/A
Year:	2021	Registration:	NSZ124	Reg Expiry:	14 Oct 2024	Engine			
WoF Expiry:	16 May 2026	Odometer:	95,120 Kms	Good No:	26076338	Oil level	~		
VIN:	LSFAM11BXMA125059	Next Service:	90,000kms	Service History	y: No	Smoke & fumes	~		
	_					Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	S SC		SC SC		Р	Performance	~		
Key:						Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust SC D D W						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SC 919 S						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S S						Performance 🖌			
Rody Inspection Commonts Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
Fuel flap damaged.						Left front	5.0 mm		mm
Chipped windscreen. F/R & rear door seals damaged						Right front	5	.0	mm
						Left rear	5	.0	mm
Conditio	ns During Body Ins	pection [.]	Dry			Right rear	5.	.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front differential & axle seal leaking. Engine oil leak.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	ats Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ard Average					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Unknown rattle noise from left dash area.						Window winder RR	~		
Air bag light on.						Rear view mirrors	~		
Engine light on. 4x4 diesel auto d/cab ute.						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		
Inspected by: Daryll Timms Date: 14 Apr 2025									
I have read and understood this condition guide. Name:									