

Report ID: 26,077,590 3 Version: 08 Jul 2025 Created:

Make:	Mazda	Model:	Bt-50	Body Style:	Utility		Pass	Fail	N/A
Year:	2018	Registration:	LGA185	Reg Expiry:	18 Jul 2025	Engine	I		L
WoF Expiry:	05 Mar 2026	Odometer:	104,502 Kms	Good No:	26077590	Oil level	~		
VIN:	MM0UR0YG100769211	Next Service:	114,000 Kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
	D		SP		D	Performance	~		
Key:				500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	S SC			210		Operation	~		
PT = paint defe	ect NP	1r			11111	Noise	~		
C = crack				The second secon		Clutch	~		
P = pin dent						CV joints			~
*= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significan			S P		D	Performance	~		
 Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Stone chip in front windscreen Left and right inner wheel arches dented						Left front	5.	0	mm
Well-side tray missing some tonneau cover pins						Right front	5.	0	mm
Front bumper detaching on both left and right side top corners						Left rear	5.	0	mm
Conditions During Body Inspection: Dry						Right rear	5.	5.0 mm	
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Slight wea	r on drivers seat				Head lights	~		
Carpote						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Blemish o	n drivers door ca	rd			Dashboard warning lights	~		
Daabbaa						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys 1			
Road Conditions During Test Drive: Dry						Central locking	~		
			21 . .			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Hoani Saunders Date: 30 May 2025									

I have read and understood this condition guide.

Name:

Signature: