

Basic Condition Guide


| • | Report ID: | 26,082,021 | Version: | 1 |
|---|------------|-------------|----------|---|
| | Created: | 15 Dec 2025 | | |

| | ОК | Requires Attention | |
|------------------------------|----------|-----------------------|--------|
| Engine | OK | Attention | 11// |
| Oil level | V | | |
| Smoke & fumes | 1 | | |
| Engine performance | 1 | | |
| Noise | V | | |
| Coolant condition | 1 | | |
| Cooling performance | 1 | | |
| Radiator / Hoses (visual) | 1 | | |
| Transmission | | | |
| Operation | V | 1 | |
| Noise | 1 | | |
| Clutch | | | |
| CV joints | 1 | | |
| Wheel bearings | 1 | | |
| Brakes | | | |
| Performance | V | | |
| Hand brake | 1 | | |
| Tyres (lowest observed tread | denth of | tvres) | |
| Left front | | | 7.5 mm |
| Right front | | - | 7.8 mm |
| Left rear | | | 6.1 mm |
| Right rear | | | 6.0 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | V | | |
| Steering performance | 1 | | |
| Shock absorbers | 1 | | |
| Air Conditioning / Heater | | | |
| Operation | V | I | |
| Electrical / Accessories | | l. | |
| Head lights | V | I | |
| Tail lights | 1 | | |
| Indicators | 1 | | |
| Dashboard warning lights | 1 | | |
| Wipers (front & rear) | 1 | | |
| Window winder FL | | | |
| Window winder FR | V | | |
| Window winder RL | 1 | | |
| Window winder RR | 1 | | |
| Rear view mirrors | 1 | 1 | |
| Radio (basic test only) | 1 | | |
| CD (basic test only) | | | ~ |
| Number of keys | 2 | | |
| Central locking | 1 | | |
| Remote locking | 1 | | |
| Sat. nav. (basic test only) | | | ~ |
| Reversing camera | 1 | | |
| g camera | | <u> </u> | |

| Mitsubishi | Model: | Triton |
|-------------|-------------------------------------|--|
| Utility | Year: | 2020 |
| MSC924 | Rego Expiry: | 09 Mar 2026 |
| 19 Mar 2026 | Odometer: | 198,157 Kms |
| 26082021 | VIN: | MMAJLKL10LH006613 |
| 213,000 Kms | Service History: | Yes |
| | Utility MSC924 19 Mar 2026 26082021 | Utility Year: MSC924 Rego Expiry: 19 Mar 2026 Odometer: 26082021 VIN: |

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

| Rey | | | | |
|-------------|-------------------|--------------|------------------|------------------------|
| S = Scratch | R = Rust | C = Crack | * = Decals | W = Significant scuffs |
| D = Dent | PT = Paint defect | P = Pin dent | SC = Stone Chips | |



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Stone chip in front windscreen

| Conditions During Body Inspection | Dry |
|---|-----|
| Under Carriage and Under Bonnet Inspection Comments | |
| 4WD | |

Interior Comments Seats: Wear on drivers side Carpets: Panels: Mark on centre console storage lid Dashboard:

General Comments

Minimal service history

| Road Conditions During Test Drive | | Dry |
|-----------------------------------|----------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Hoani Saunders | |
| Published by: | Malcolm Thomas | |
| Inspection Date: | 15 Dec 2025 | |

| I have read and understood |
|----------------------------|
| this condition guide: |

| NAME | | | |
|------|--|--|--|

| SIGNATURE | | |
|-----------|--|--|