

•	Report ID:	26,082,239	Version:	1
	Created:	27 Nov 2025		

ED T	uner	S Bas	ic Condition Guide	Created: 27 Nov		rsion: I		
Make:	BMW	Model:	1 Series		OK	Requires Attention	N/A	
Body Style:	Hatchback	Year:	2012	Engine	<u> </u>	7 teterition	14,71	
Rego No.:	GPP682	Rego Expiry:	26 Feb 2025	Oil level	V		1	
WoF Expiry:	29 Jan 2026	Odometer:	126,735 Kms	Smoke & fumes	V			
Good No.:	26082239	VIN:	WBA1A52030E610874	Engine performance	V			
Next Service:	0	Service History:	No	Noise	V			
lote: This report	•			Coolant condition	V			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.			Cooling performance			1		
			Radiator / Hoses (visu					
ey - Scratch 1	D = Dust	Crack * - Doc	ols W - Cignificant scuffs	Transmission				
S = Scratch $R = Rust$ $C = Crack$ $* = Decals$ $W = Significant scuffsD = Dent$ $PT = Paint defect$ $P = Pin dent$ $SC = Stone Chips$			Operation	V	I	Ī		
				Noise	· ·			
S		S	S	Clutch		<u> </u>	1	
				CV joints	V			
			S SC	Wheel bearings	V			
s sc				Brakes				
	119/			Performance	V		Г	
				Hand brake	V			
S SC				Tyres (lowest observed tread depth of tyres)				
		Left front		2.2 mr				
S S S S D Note: some defects and blemishes may not be displayed in the diagram				Right front		3.2 mr		
				Left rear		4.2 mr		
				Right rear		5.0 m		
				Spare	Yes	Yes		
Body Inspect	tion Comments			Suspension	,			
Rear bumper	detached on left side			Suspension perform	ance 🗸			
				Steering performance	e 🗸			
				Shock absorbers	·			
Conditions Du	uring Body Inspection		Dry	Air Conditioning / H	leater			
	ge and Under Bonne	t Inspection Comr	nents	Operation	· ·			
				Electrical / Accessor	ries	•		
				Head lights		V		
				Tail lights	V			
Interior Comments				Indicators	V			
Seats:	Average			Dashboard warning	lights 🗸			
Carpets:	Average			Wipers (front & rear)	·			
Panels:	Average			Window winder FL	·			
Dashboard:	Average			Window winder FR	· ·			
General Comments			Window winder RL	· ·				
Right headlight bulb not working				Window winder RR	/			
				Rear view mirrors	/			
				Radio (basic test only	<i>'</i>)			

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Timing Cha	in	
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Kyle Kelly			
Published by:	Malcolm Thomas			
Inspection Date:	06 Nov 2025			

I have read and understood			
this condition guide:	NAME	SIGNATURE	

CD (basic test only)

Number of keys Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

1 2

•

•