

## **Basic Condition Guide**

'	Report ID:	26,082,358	Version:	1
	Created:	19 Nov 2025		

	ullei	<u> </u>		Created:	19 Nov
Make:	Mitsubishi	Model:	Triton		
Body Style:	Utility	Year:	2017	Engine	
Rego No.:	KTA711	Rego Expiry:	20 Jun 2026	Oil level	
WoF Expiry:	03 Dec 2026	Odometer:	225,172 Kms	Smoke & f	umes
Good No.:	26082358	VIN:	MMAJYKL10HH016562	Engine per	
Next Service:	235100	Service History:	Yes	Noise	Torritanc
Note: This report is	not a warranty	,	•	Coolant co	ndition
			arts have not been dismantled or h from cold. The Vendor recommends a	Cooling pe	
full mechanical insp	ection prior to purchase an	d this can be arranged f	or an additional charge.	- 31	
Key				Radiator / Transmiss	
	$= Rust \qquad C = C$				
D = Dent P	T = Paint defect P = P	in dent SC = Sto	ne Chips	Operation	
sc		P	SC	Noise	
				Clutch	
			SSC	CV joints	
S SC W				Wheel bea	rings
- A	18			Brakes	
	M = 1	$\mathbb{N}$	R SC	Performan	ice
				Hand brak	ie .
D SC				Tyres (lowest obser	
				Left front	
				Right front	t
				Left rear	
		D	D	Right rear	
Note: some defects	and blemishes may not be	displayed in the diagra	am	Spare	
Body Inspecti	on Comments			Suspensio	on
Small stone ch	ip in front windscreen			Suspensio	n perforn
				Steering p	erforman
				Shock abs	orbers
Conditions Du	ring Body Inspection		Dry	Air Condi	tioning/
Under Carria	ge and Under Bonnet	Inspection Comm	nents	Operation	
				Electrical	/ Accesso
				Head light	:s
				Tail lights	
Interior Comr	nents			Indicators	
Seats:	Wear on drivers s	eat		Dashboard	d warninc
Carpets:	Good			Wipers (fro	
Panels:	Good			Window w	
Dashboard:	Wear on steering	wheel		Window w	
General Com				Window w	
Partial service h				Window w	
T ditial convice i	liotory				
				Rear view	
Daniel Co., 199	Davis Tay D	Dn		Radio (bas	
	ns During Test Drive	Dry Timing Chain		CD (basic t	
Engine Timing		Timing Chain		Number of	
Evidence of Ca	m Belt Replacement	Yes	No Kms	Central loc	king

	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	/		
Engine performance	<ul><li>V</li><li>V</li><li>V</li></ul>		
Noise	/		
Coolant condition	/		
Cooling performance	<b>✓</b>		
Radiator / Hoses (visual)	<b>✓</b>		
Transmission			
Operation	/		
Noise	/		
Clutch			<b>/</b>
CV joints	<b>✓</b>		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	<b>/</b>		
Tyres (lowest observed tread de	pth of	tyres)	
Left front			1.5 mm
Right front			1.1 mm
Left rear		3	3.3 mm
Right rear		3	3.4 mm
Spare	Yes		
Suspension			
Suspension performance	<b>✓</b>		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories	_		
Head lights	/		
Tail lights	/		
Indicators	<b>V</b>		
Dashboard warning lights	/		
Wipers (front & rear)	<b>V</b>		
Window winder FL	<b>/</b>		
Window winder FR	<b>/</b>		
Window winder RL	<b>V</b>		
Window winder RR			
Rear view mirrors	<b>V</b>		
Radio (basic test only)	<b>V</b>		
CD (basic test only)	2		
Number of keys	2		
Central locking	/		
Remote locking	<b>✓</b>		
Sat. nav. (basic test only)			
Reversing camera	/		

have read and understood
this condition guide:

Inspection Date: 11 Nov 2025

Inspected by:

Published by:

N	Δ	N	۱F

Hoani Saunders

Malcolm Thomas

SIGNATURE