

Report ID:	26,082,890	Version:	1
Created:	10 Dec 2025		

		Roc	ic Condition Guide	Report I
	urne	<u> </u>		Created
Make:	Subaru	Model:	Outback	
Body Style:	SUV	Year:	2023	
Rego No.:	QFA357	Rego Expiry:	03 Jan 2026	Engine
WoF Expiry:	01 Sep 2026	Odometer:	53,317 Kms	Oil level
Good No.:	26082890	VIN:	JF2BT9KL3PG047552	Smoke 8
Next Service:	57,000 Kms	Service History:	Yes	Engine
Note: This report i	s not a warranty	,		Noise Coolant
			arts have not been dismantled or 'h from cold. The Vendor recommends a	Cooling
	pection prior to purchase a			Radiato
Key				Transm
	R = Rust $C = Rust$ $C = Rust$	Crack *= Deca	als W = Significant scuffs one Chips	Operation
) = Dent F	FT = Paint defect F = 1	Findent 3C = 3to	ine Criips	Noise
P(_		s s	S	Clutch
				CV joint
	\mathcal{O}		(O) SC	Wheel b
S SC /				Brakes
				Perform
				Hand br
S SC	HA			Tyres (lo
	118 OF			Left from
			(Q)	Right fro
				Left rea
s		S S	SSC	Right re
Note: some defect	s and blemishes may not b	e displayed in the diagr	am	Spare
Body Inspect	tion Comments			Suspen
				Suspens
				Steering
				Shock al
Conditions Du	uring Body Inspection		Wet	Air Con
Under Carria	ge and Under Bonne	t Inspection Comn	nents	Operation
4WD				Electric
				Head lig
				Tail light
Interior Com	ments			Indicato
Seats:	Good			Dashbo
Carpets:	Good			Wipers (
Panels:	Good			Window
Dashboard:	Good			Window
General Com	ments			Window
				Mindou

	ОК	Requires Attention	N/A
Engine	OIC	Attention	11//1
Oil level	V		
Smoke & fumes	~		
Engine performance		 	
Noise	\(\times \)	-	
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	·		
Noise	1		
Clutch		-	
CV joints	1		
Wheel bearings	1		
Brakes			
Performance	· ·	l	
Hand brake	1		
Tyres (lowest observed tread of	lenth of	tures)	
Left front	Eptiloi		3.0 mm
Right front			3.0 mm
Left rear			1.0 mm
Right rear		-	3.0 mm
Spare	Yes		
Suspension	100		
Suspension performance	· ·		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories		l	
Head lights	·		
Tail lights	1		
Indicators	1		
Dashboard warning lights	V		
Wipers (front & rear)	~		
Window winder FL	~	<u> </u>	
Window winder FR	~	-	
Window winder RL	V		
Window winder RR	V	 	
Rear view mirrors	V	 	
Radio (basic test only)	V	 	
CD (basic test only)	+	-	
Number of keys	2	<u> </u>	
Central locking	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	I	
Remote locking	<i>J</i>		
Sat. nav. (basic test only)	+	-	
Reversing camera	1	 	_
neversing carriera			

Road Condition	s During Test Drive	Wet		
Engine Timing Mechanism		Timing Chain		
Evidence of Cam Belt Replacement		Yes	No	Kms
Inspected by:	Hoani Saunders			
Published by:	Robert Chardon		·	
Inspection Date:	03 Dec 2025			

I have read and understood
this condition guide:

NZ	M	

S	IG	N	ΔT	ΓIJ	R	F