


Basic Condition Guide

•	Report ID:	26,082,959	Version:	1
	Created:	05 Dec 2025		

	01/	Requires	N1/A
Engine	OK	Attention	N/A
Oil level	1		
Smoke & fumes	1		
	1		
Engine performance	V		
Noise	~		
Coolant condition			
Cooling performance	V		
Radiator / Hoses (visual)		L	
Transmission		I	П
Operation	/		
Noise	/		
Clutch			
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread	depth of	tyres)	
Left front		6	6.0 mm
Right front		6	6.1 mm
Left rear		6	8.8 mm
Right rear		6	6.7 mm
Spare	N/A		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories		<u> </u>	
Head lights	/		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	1		
Window winder RL			
Window winder RR			1
Rear view mirrors	1	<u> </u>	<u> </u>
Radio (basic test only)	1	 	
CD (basic test only)	1	-	
Number of keys	1	<u> </u>	Ь
Central locking	1	<u> </u>	
Remote locking	1		
Sat. nav. (basic test only)	1		
Reversing camera		<u> </u>	

	Ulliel	5	o Condition Calac
Make:	Honda	Model:	CR-Z
Body Style:	Hatchback	Year:	2010
Rego No.:	QNT197	Rego Expiry:	19 May 2025
WoF Expiry:	05 Dec 2026	Odometer:	116,944 Kms
Good No.:	26082959	VIN:	7AT08GCLX23018497
Next Service:	119,300 Kms	Service History:	No
diagnostic testing ui	only. Consideration is mad	een driven up to 50km/l	arts have not been dismantled or h from cold. The Vendor recommends a or an additional charge.
Key			
S = Scratch R	= Rust $C = C$	`rack * = Deca	ls W = Significant scuffs

S = ScratchR = RustC = Crack= Decals W = Significant scuffs D = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $\,$

Body Inspection Comments

Surface rust in boot jamb

Hole in front bumper covered with tape

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

2WD

Surface rust on strut towers

Interior Comments		
Seats: Wear on front seats		
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
General Comments		

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Hoani Saunders	
Published by:	Malcolm Thomas	
Inspection Date:	04 Dec 2025	

I	have	read	and	understoo	od
t	his co	nditi	on a	uide.	

NAME		

NATURE		