

•	Report ID:	26,083,027	Version:	1
	Created:	31 Dec 2025		

	ОК	Requires Attention	N/A
Engine			
Oil level	<b>/</b>		
Smoke & fumes	<b>/</b>		
Engine performance	✓ ✓		
Noise	<b>/</b>		
Coolant condition	<b>/</b>		
Cooling performance	<b>/</b>		
Radiator / Hoses (visual)	<b>/</b>		
Transmission			
Operation	<b>/</b>		
Noise	<b>/</b>		
Clutch			1
CV joints	<b>/</b>		
Wheel bearings	<b>/</b>		
Brakes			
Performance	/		
Hand brake	<b>/</b>		
Tyres (lowest observed tread d	epth of	tyres)	
Left front	•		6.1 mm
Right front		(	6.4 mm
Left rear			5.1 mm
Right rear			5.4 mm
Spare	N/A		
Suspension			
Suspension performance	<b>/</b>		
Steering performance	<b>/</b>		
Shock absorbers	<b>/</b>		
Air Conditioning / Heater		<u> </u>	
Operation	<b>✓</b>		
Electrical / Accessories			
Head lights	<b>V</b>		
Tail lights	<b>/</b>		
Indicators	<b>V</b>		
Dashboard warning lights		<b>V</b>	
Wipers (front & rear)	<b>✓</b>		
Window winder FL	<b>/</b>		
Window winder FR	<b>/</b>		
Window winder RL	<b>✓</b>		
Window winder RR	<b>V</b>		
Rear view mirrors	<b>/</b>		
Radio (basic test only)	/		
CD (basic test only)	<b>/</b>		
Number of keys	1		
Central locking	<b>/</b>		
Remote locking	<b>/</b>		
Sat. nav. (basic test only)			~
Reversing camera	<b>/</b>		

_					
<b>O</b> TI	urner	S Basi	Basic Condition Guide		
Make:	Mazda	Model:	Axela		
Body Style:	Hatchback	Year:	2010		
Rego No.:	PJL304	Rego Expiry:	11 Jul 2026		
WoF Expiry:	07 Aug 2026	Odometer:	112,313 Kms		
Good No.:	Good No.: 26083027		7AT0C13JX22112232		
Next Service: 108,095 Kms		Service History:	No		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					
<b>Key</b> S = Scratch R:	= Rust	rack *=Deca	ls W = Significant scuffs		
5 Sciatori II	$\Gamma = \text{Paint defect}  P = \text{Pi}$		o.gcancocans		
SC W SD S					
S SC W			SSC		

SC W	S D	
S SC W		S SC
		SP
sc		
PW	) SP	P

Note: some defects and blemishes may not be displayed in the diagram

## **Body Inspection Comments**

Front bumper detaching on sides

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				
OMD				

Interior Comments				
Seats:	Wear on front seats			
Carpets:	Good			
Panels: Good				
Dashboard: Good				

## **General Comments**

i-Stop warning light flashing

Front interior roof light buttons detached

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		Yes No Kms	
Inspected by:	Hoani Saunders		
Published by:	Malcolm Thomas		
Inspection Date:	08 Dec 2025		

I have read and understood
this condition guide:

NAME			

SIGNATURE		