

Basic Condition Guide

| • | Report ID: | 26,083,089 | Version: | 1 |
|---|------------|-------------|----------|---|
| | Created: | 11 Dec 2025 | | |

| | Dille | Da s | | Created: | 11 Dec 2025 | | | | |
|--|---|---|-----------------------------|--|------------------|----------|--------------|--------------|--|
| M.I. | NAME OF THE PARTY | AA . d.d | Taite | | | | Requires | | |
| Make: | Mitsubishi | Model: | Triton | | | OK | Attention | N/A | |
| Body Style: | Utility | Year: | 2017 | Engine | | | | | |
| Rego No.: | KZZ653 | Rego Expiry: | 31 Jan 2026 | Oil level | | / | | | |
| WoF Expiry: | 21 Nov 2026 | Odometer: | 127,349 Kms | Smoke & fumes | | / | | | |
| Good No.: | 26083089 | VIN: | MMAJYKK10HH022342 | Engine per | formance | / | | | |
| Next Service: | 133,000 Kms | Service History: | Noise | | / | | | | |
| ote: This report is his report is a guide | only. Consideration is ma | ade for age and mileage. | Coolant co | ndition | / | | | | |
| iagnostic testing ur ıll mechanical insp | ndertaken. The vehicle has ection prior to purchase a | s been driven up to 50kn and this can be arrange | Cooling performance | | / | | ļ | | |
| ey | | | Radiator / Hoses (visual) | | / | | | | |
| - | = Rust C = | Crack *= Dee | cals W = Significant scuffs | Transmiss | ion | | , | | |
| = Dent P | T = Paint defect P = | Pin dent $SC = St$ | tone Chips | Operation | | / | | <u> </u> | |
| S | | s s | SC | Noise | | / | | <u> </u> | |
| $\overline{}$ | | \top | | Clutch | | | | | |
| | -00 | | | CV joints | | | | V | |
| S SC | | | | Wheel bea | / | | | | |
| | 18 | | | Brakes | | | _ | | |
| 1 | M = 1 | $\parallel \parallel \parallel \parallel$ | | Performan | ce | / | | | |
| | | | | Hand brak | e | / | | \bot | |
| S P SC | | | | Tyres (lowest observed tread depth of tyres) | | | | | |
| | | | | Left front | | | | 7.0 m | |
| | | | | Right front | | | | 6.5 m | |
| | | | | Left rear | | 5.5 | | 5.5 m | |
| | | SP | Right rear | | | | 6.0 m | | |
| lote: some defects | and blemishes may not | be displayed in the diag | gram | Spare | | Yes | | | |
| , , | on Comments | | | Suspension | n | | 1 | | |
| Left canopy loc | k broken | | | Suspensio | n performance | / | | | |
| | | | | Steering p | erformance | / | | | |
| | | | | Shock abso | | / | | | |
| | ring Body Inspection | | Dry | Air Condit | ioning / Heater | | | | |
| | ge and Under Bonn | et Inspection Com | ments | Operation | | / | | \bot | |
| 2WD | | | | | Accessories | | 1 | | |
| | | | | Head light | S | / | | _ | |
| | | | | Tail lights Indicators | | / | | 1 | |
| Interior Comments | | | | | | / | | ↓ | |
| Seats: | | ned. Front left hea | adrest missing | | l warning lights | / | | — | |
| Carpets: | Average | | Wipers (fro | | / | | <u> </u> | | |
| Panels: | Average | | | Window w | | / | | ₩ | |
| Dashboard: | Average | | Window w | | <u>/</u> | | | | |
| General Comr | ments | | | Window w | | <u>/</u> | | | |
| | | | | Window w | | <u>/</u> | | 1 | |
| | | | | Rear view | | / | | | |
| | | | | ic test only) | / | | _ | | |
| | ns During Test Drive | - | CD (basic t | | <u>/</u> | | | | |
| Engine Timing | | Timing Chain | Number of | | 1 | 1 | | | |
| Evidence of Cam Belt Replacement Yes No Kms | | | | | king | / | | 1 | |
| Inspected by: Hoani Saunders | | | | Remote lo | _ | / | | | |
| Published by: Malcolm Thomas | | | | Sat. nav. (b | asic test only) | | | - | |
| 1 2 14 5 0005 | | | | | | | 1 | 1 | |

I have read and understood this condition guide:

Inspection Date: 11 Dec 2025

NAME

SIGNATURE

Reversing camera