


Basic Condition Guide

•	Report ID:	26,083,101	Version:	1
	Created:	13 Dec 2025		

Make:	Holden	Model:	Commodore
Body Style:	Wagon	Year:	2019
Rego No.:	MDK571	Rego Expiry:	09 May 2026
WoF Expiry:	15 May 2026	Odometer:	216,702 Kms
Good No.:	26083101	VIN:	W0VZM8EC7J1176624
Next Service:	223,000 Kms	Service History:	Yes
Note: This report is not a warranty			

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key S = ScratchR = RustC = Crack* = DecalsW = Significant scuffs D = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram $% \left(1\right) =\left(1\right) \left(1\right$

Body Inspection Comments

Holes in front and rear bumpers Small stone chips in front windscreen

Conditions During Body Inspection	Dry		
Under Carriage and Under Bonnet Inspection Comments			

2WD

	Interior Comments		
Seats: Slight wear on front seats		Slight wear on front seats	
Carpets: Slight wear on drivers left side foot rest			
Panels: Screw holes in centre console and boot lid panel Dashboard: Screw holes on dashboard		Screw holes in centre console and boot lid panel	
		Screw holes on dashboard	

General Comments

I have read and understood this condition guide:

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Hoani Saunders	
Published by:	Robert Chardon	
Inspection Date:	10 Dec 2025	

NAME	

	ОК	Requires Attention	N/A
Engine			
Oil level	~		
Smoke & fumes	/		
Engine performance	V		
Noise	~		
Coolant condition	~		
Cooling performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	✓		
Noise	/		
Clutch			~
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		2	2.7 mm
Right front		2	2.8 mm
Left rear		4	1.0 mm
Right rear		4	1.5 mm
Spare	Yes		
Suspension			
Suspension performance	/		
Steering performance	/		
Shock absorbers	/		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	~		
Tail lights	/		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	/		
Window winder FL	\(\tau \)		
Window winder FR	/		
Window winder RL	/		
Window winder RR	/		
Rear view mirrors	/		
Radio (basic test only)	/		
CD (basic test only)			/
Number of keys	3		
Central locking	/		
Remote locking	/		
Sat. nav. (basic test only)			~
Reversing camera	/		

SIGNATURE		