

Report ID: 26,083,516		Version:	2
Created:	24 Dec 2025		

Yes

1

1

1

1 1

1 1

1

1

1

1

Requires

Attention

N/A

3.5 mm

5.5 mm

3.5 mm

3.5 mm

		Posi	a Condition Cuida	Report ID:	26,083,516	Ve	ersion:
	nue	S Basi	c Condition Guide	Created:	24 Dec 2025		
Make:	Mitsubishi	Model:	ASX			ОК	Requ
Body Style:	SUV	Year:	2021	Engine		- OK	Atte
Rego No.:	NUW698	Rego Expiry:	17 Feb 2026	Oil level		/	
WoF Expiry:	24 Dec 2026	Odometer:	79,770 Kms	Smoke & fu	ımes	<i>-</i>	\vdash
Good No.:	26083516	VIN:	JMFXTGA2WMU018738	Engine per		1	+-
Next Service:	63,675 Kms	Service History:	Yes	Noise	Torriance	1	
Note: This report is	not a warranty		,		Coolant condition		+
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a					erformance	V V	+-
full mechanical inspe	ection prior to purchase an	d this can be arranged f	or an additional charge.		Hoses (visual)	1	+
Key				Transmiss			
	= Rust C = C		3		1011		Т
D = Dent P	$\Gamma = Paint defect P = P$	in dent SC = Sto	ne Cnips	Operation		_	1
S		s s	S	Noise		/	-
				Clutch			
				CV joints		/	
	MA UT			Wheel bea	rings	1	
S SC				Brakes			
	MC 11.			Performan	ce	1	Ι
				Hand brak	e	1	
D	18			Tyres (low	est observed tread d	epth of	tyres)
				Left front			

Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Stone chip in front windscreen

Conditions During Body Inspection	Dry			
Under Carriage and Under Bonnet Inspection Comments				
2WD				

Interior Comments			
Seats: Good			
Carpets:	Slight wear on drivers floor mat		
Panels:	Good		
Dashboard:	Good		

General Comments

One key remote button will not work but will start the car lights up with little red dot on the remote

Road Condition	s During Test Drive	Dry
Engine Timing I	Mechanism	Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Hoani Saunders	
Published by:	Malcolm Thomas	
Inspection Date:	22 Dec 2025	

Engine Timing Mechanism	Timing Chain		Number of keys	2	
Evidence of Cam Belt Replac	cement Yes No	Kms	Central locking	~	
Inspected by: Hoani Sa	unders		Remote locking	V	
Published by: Malcolm	Thomas		Sat. nav. (basic test only)		/
Inspection Date: 22 Dec 20	025		Reversing camera	V	
I have read and understood this condition guide:	NAME	s	SIGNATURE		

S

S

Right front

Left rear

Right rear

Suspension

Suspension performance

Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR

Radio (basic test only) CD (basic test only)

Rear view mirrors

Steering performance

Shock absorbers

Operation

Head lights

Tail lights Indicators

Spare