


Make:	MG	Model:	ZS
Body Style:	SUV	Year:	2021
Rego No.:	NRP738	Rego Expiry:	06 Aug 2026
WoF Expiry:	16 Sep 2026	Odometer:	50,093 Kms
Good No.:	26083544	VIN:	LSJW74090MZ063501
Next Service:	69,250 Kms	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Conditions During Body Inspection	Dry
Under Carriage and Under Bonnet Inspection Comments	
2WD	

Seats:	Small rip on driver seat
Carpets:	Good
Panels:	Good
Dashboard:	Good

Road Conditions During Test Drive		Dry	
Engine Timing Mechanism		Timing Chain	
Evidence of Cam Belt Replacement		☐ Yes	☐ No
Inspected by:	Hoani Saunders		
Published by:	Malcolm Thomas		
Inspection Date:	22 Dec 2025		

I have read and understood
this condition guide:

NAME _____

SIGNATURE