

_	Report ID: 26,111,702		Version:	1
	Created:	15 Dec 2025		

OK

Requires Attention

N/A

<b>4</b> )Ti	urner	Basi	c Condition Guide	Report ID: 26,111,702		
	oniei			Created: 15 Dec 2025		
Make:	Hyundai	Model:	lload			
Body Style:	Van	Year:	2019	Fueine		
Rego No.:	MGA156	Rego Expiry:	03 Jul 2026	Engine		
WoF Expiry:	23 Jun 2026	Odometer:	85,751 Kms	Oil level		
Good No.:	26111702	VIN:	KMFWBX7KMLU088769	Smoke & fumes		
Next Service:	due	Service History:	Yes	Engine performance		
ote: This report is	not a warranty	,	<u> </u>	Noise		
nis report is a guide	only. Consideration is made		arts have not been dismantled or h from cold. The Vendor recommends a	Cooling performance		
	ection prior to purchase an			Cooling performance		
ey				Radiator / Hoses (visual)		
	= Rust C = C			Transmission		
= Dent P	T = Paint defect P = P	in dent SC = Sto	ne Chips	Operation		
		S D D		Noise		
				Clutch		
	$\sim$		S	CV joints		
C				Wheel bearings		
$ \beta$	18			Brakes		
1		$\parallel \parallel \perp \perp$	SC	Performance		
				Hand brake		
SC				Tyres (lowest observed tread		
				Left front		
				Right front		
		S D D		Left rear		
				Right rear		
	and blemishes may not be	displayed in the diagra	am	Spare		
, ,	on Comments			Suspension		
Holes on dashb Front tyres side	ooard wall minor cracked			Suspension performance		
•	area interior plywood			Steering performance		
Remote key da				Shock absorbers		
Conditions Du	ring Body Inspection		Wet	Air Conditioning / Heater		
	je and Under Bonnet	Inspection Comm	nents	Operation		
Rear wheel driv	-			Electrical / Accessories		
Engine oil leaks	i			Head lights		
				Tail lights		
Interior Comn	nents			Indicators		
Seats:	ats: Good			Dashboard warning lights		
Carpets: Good			Wipers (front & rear)			
Carpets:	Good					
Panels:	Average			Window winder FL		
•	1.			Window winder FL Window winder FR		
Panels:	Average Average					
Panels: Dashboard: General Comr gnition barrel n	Average Average			Window winder FR		

Radiator / Hoses (visual)	<b>/</b>		
Transmission			
Operation	~		
Noise	~		
Clutch			1
CV joints			1
Wheel bearings	~		
Brakes			
Performance	~		
Hand brake	~		
Tyres (lowest observed tread	depth of ty	/res)	
Left front			5.5 mr
Right front			5.5 mr
Left rear			4.5 mr
Right rear			4.5 mr
Spare	Yes		
Suspension	•		
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			•
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	/		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			1
Window winder RR			V
Rear view mirrors	~		
Radio (basic test only)	V		
CD (basic test only)			<b>/</b>
Number of keys	1		
Central locking	V		
Remote locking		<b>/</b>	
Sat. nav. (basic test only)			V
Reversing camera	1		$\top$

I have read and understood
this condition quide:

Road Conditions During Test Drive

Evidence of Cam Belt Replacement

Inspection Date: 15 Dec 2025

Xinghui Lin

Xinghui Lin

Engine Timing Mechanism

Inspected by:

Published by:

NAME	F		

Wet

Timing Chain

No

Yes

Left rear suspension/area knocking noise when test drivingg

S	IG	N	ΔT	u	R	F

Kms