


Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2020
Rego No.:	NEB146	Rego Expiry:	29 Nov 2026
WoF Expiry:	06 Oct 2026	Odometer:	149,593 Kms
Good No.:	26112982	VIN:	MPBUMEF50LX296172
Next Service:	157,000 Kms	Service History:	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Well side tray missing, rear suspension will misbehave due to minimal weight on rear  
 All rear components to refit (Tail Lights, Reversing Camera, Parking Sensors & Rear plate/ Plate Light)

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**
**Interior Comments**

Seats:	Poor
Carpets:	Average
Panels:	Average
Dashboard:	Average

**General Comments**

Rear Belt Monitor Malfunction warning displayed on dash  
 Passenger door ajar sensor faulty, unable to lock vehicle due to this

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Jaden Jenkins
Published by:	Jaden Jenkins
Inspection Date:	10 Feb 2026

I have read and understood  
 this condition guide:

NAME \_\_\_\_\_

Report ID:	26,112,982	Version:	1
Created:	10 Feb 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front		9.5 mm	
Right front		9.5 mm	
Left rear		5.5 mm	
Right rear		5.5 mm	
Spare		Yes	
<b>Suspension</b>			
Suspension performance		✓	
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights		✓	
Indicators		✓	
Dashboard warning lights		✓	
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking		✓	
Remote locking		✓	
Sat. nav. (basic test only)			✓
Reversing camera			✓

SIGNATURE \_\_\_\_\_