


Make:	Hyundai	Model:	Tucson
Body Style:	SUV	Year:	2021
Rego No.:	NUA396	Rego Expiry:	13 Apr 2026
WoF Expiry:	01 Nov 2026	Odometer:	101,523 Kms
Good No.:	26116615	VIN:	TMAJB81DMNJ107869
Next Service:	109000	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Conditions During Body Inspection	Dry
-----------------------------------	-----

2wd

Seats:	stains
Carpets:	Average
Panels:	scratch marks
Dashboard:	Average

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Uriah Pepene		
Published by:	Uriah Pepene		
Inspection Date:	17 Dec 2025		

NAME _____

SIGNATURE