

Basic Condition Guida

-	Report ID:	26,116,658	Version:	1
	Created:	17 Dec 2025		

	ntuet	' S Basi	c Condition Guide	Created:	17 Dec 2025			
				Cicatea.	200 2020			
Make: Toyota Model: Hilux		Hilux			ОК	Requires Attention	N/A	
Body Style:	Utility	Year:	2014	Engine			7 itterition	14// 1
Rego No.:	HQC429	Rego Expiry:	25 Aug 2026	Oil level		V		
WoF Expiry:	05 Nov 2026	Odometer:	250,206 Kms	Smoke & fu	ımes	/		
Good No.: 26116658		VIN:	MR0FZ22G001086198	Engine performance		/		
Next Service:	225800	Service History:	Yes	Noise		/		
Note: This report is not a warranty					ndition	1		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a					rformance	1		
full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Radiator / Hoses (visual)			
Key S = Scratch R:	= Rust C = C	rack *= Deca	ls W = Significant scuffs	Transmission				
	= nust		_	Operation		1		
				Noise		1		
S SC	S	* SC S * SC		Clutch		/		
				CV joints		/		
				Wheel bea	rings	~		
S SC W				Brakes				
				Performan	ce	/		
				Hand brake	2	1		
S SC	SSC				Tyres (lowest observed tread depth of tyres)			
								8 mm
			(Q)	Right front				8 mm
	\angle			Left rear				9 mm
S SC S D * SC			Right rear				9 mm	
Note: some defects and blemishes may not be displayed in the diagram						Yes		
Body Inspection Comments					Suspension			
Right side step bent/dent in rr cab/radio screen cracked/airbag light on				Suspension	n performance	~		
				Steering pe	erformance	1		
				Shock abso	orbers	1		
Conditions During Body Inspection Dry				Air Conditioning / Heater				
Under Carriage and Under Bonnet Inspection Comments				Operation		1		
4x4/major engine oil leak further investigation needed/underbody surface rust/under				Electrical / Accessories				
cover bent/			Head light:	5	/			
				Tail lights		/		

Interior Comments			
Seats: Average			
Carpets:	hole on drivers side		
Panels:	scratch marks		
Dashboard: scratch marks and holes			
General Com	General Comments		

Clutch engagement at top of pedal further investigation needed/

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Cambelt		
Evidence of Can	Evidence of Cam Belt Replacement		V No	Kms
Inspected by:	Uriah Pepene			
Published by:	Uriah Pepene			
Inspection Date:	17 Dec 2025			

I have read and understood				
this condition guide:	NAME	SIGNATURE		

Indicators

Dashboard warning lights Wipers (front & rear)

Window winder FL Window winder FR Window winder RL

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. nav. (basic test only) Reversing camera

1 1

1

1

1 1

1

1

1