

Basic Condition Guide

•	Report ID:	26,116,670	Version:	1	
	Created:	17 Dec 2025			

Urners _		S Basi	Basic Condition Guide		Created: 17 Dec 2025					
Make:	Toyota	Model:	Hilux				Requires			
,		2013			OK	Attention	N/A			
		Rego Expiry:	19 Aug 2026	Engine						
WoF Expiry:	11 Jul 2026	Odometer:	145,469 Kms	Oil level						
Good No.:	26116670	VIN:	MR0FZ22G801076437			✓				
Next Service:	151000	Service History:	Yes	Engine per	formance	✓				
						✓				
Note: This report is a guide	only. Consideration is made	e for age and mileage. Pa	arts have not been dismantled or	Coolant co	ndition					
diagnostic testing unfull mechanical inspe	dertaken. The vehicle has b ection prior to purchase and	een driven up to 50km/h d this can be arranged fo	n from cold. The Vendor recommends a or an additional charge.	Cooling pe	rformance	~				
Key				Radiator / I	Hoses (visual)	~				
	= Rust C = C	rack * = Deca	ls W = Significant scuffs	Transmiss	ion					
D = Dent PT	= Paint defect $P = Pi$	in dent SC = Stor	ne Chips	Operation		~				
SSC	9	* SC S SC	SSC	Noise	Noise					
330		330	330	Clutch				/		
	8		S D SC	CV joints		/				
				Wheel bea	rings	~				
S SC				Brakes						
	Mr 11.			Performan	ce	/				
S SC S SC					2	/				
					Tyres (lowest observed tread depth of tyres)					
						7 mn				
						7 m				
						7 mr				
S SC S SC S SC				Right rear	Right rear 7			7 mm		
Note: some defects a	and blemishes may not be	displayed in the diagra	ım	Spare Yes						
Body Inspection	on Comments			Suspensio	n					
Rear bumper m	ajor impact damage/r	ight hand step bent	t/tag in and out device installed/	Suspension	n performance	~				
				Steering pe	erformance	/				
				Shock abso	orbers	/				
Conditions During Body Inspection				Air Conditioning / Heater						
Under Carriage and Under Bonnet Inspection Comments				Operation		✓				
4x4/transmission	n leak further investig	ation needed/major	r underbody surface rust/	Electrical /	Accessories					
				Head light:	5	/				
				Tail lights		/				
Interior Comm	ents			Indicators		✓				
Seats:	Average			Dashboard	warning lights	1				
Carpets:	Average			Wipers (fro	nt & rear)	/				

Interior Comments						
Seats:	Average					
Carpets:	Average					
Panels:	ratch marks					
Dashboard:	d: holes,glove box misaligned scratch marks					
General Comments						

Road Condition	s During Test Drive	Dry		
Engine Timing I	Mechanism	Cambelt		
Evidence of Cam Belt Replacement		✓ Yes	No	122,757 Kms
Inspected by:	Uriah Pepene			
Published by:	Uriah Pepene			

SIGNATURE		

1

1

<u>ノ</u>

2

<u>ノ</u>

Window winder FL
Window winder FR

Window winder RL

Window winder RR
Rear view mirrors
Radio (basic test only)

CD (basic test only)

Number of keys Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

I	ha	ve	rea	d	an	d	un	de	ers	to	OC	Į
t	his	co	nd	itio	on	g	uic	de:				

Inspection Date: 17 Dec 2025