

Basic Condition Guide

•	Report ID:	26,116,689	Version:	1
	Created:	17 Dec 2025		

	ntue	S Bas	Created: 17 Dec 2025					
Make:	Toyota	Model:	Hilux			Requires		
Body Style:	Utility	Year:	2013	Engine	OK	Attention	N/A	
Rego No.:	HAM184	Rego Expiry:	28 Aug 2026	Engine				
WoF Expiry:	20 Nov 2026	Odometer:	158,666 Kms	Oil level	V			
Good No.:	26116689	VIN:	MR0FZ22G001197396	Smoke & fumes	<i>'</i>	<u> </u>		
Next Service:	173000	Service History:	Yes	Engine performance	V			
lote: This report is	not a warranty	,	Noise	-				
his report is a guide	only. Consideration is ma	ade for age and mileage. P	Parts have not been dismantled or In from cold. The Vendor recommends a	Coolant condition	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
ıll mechanical insp	ection prior to purchase a	and this can be arranged	Cooling performance	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
Key				Radiator / Hoses (visual)				
		Crack *= Deca		Transmission				
D = Dent P	T = Paint defect P =	Pin dent $SC = Sto$	one Chips	Operation	/			
S SC		S * SC S SC	SSC	Noise	/			
				Clutch	/			
	\sim \sim		SSC	CV joints	/			
S SC				Wheel bearings	/			
$\overline{}$	18			Brakes				
				Performance	/			
				Hand brake	/			
s sc				Tyres (lowest observed tread depth of tyres)				
			SPSC	Left front	4.5 mm			
			3730	Right front			1.5 mr	
			Left rear	5 mm				
S SC		s sc s sc	Right rear	5 mm				
ote: some defects	and blemishes may not l	be displayed in the diagr	am	Spare	Yes			
Body Inspecti	on Comments			Suspension				
Sign in and out	device installed/			Suspension performance	/			
				Steering performance	/			
				Shock absorbers	/			
Conditions Du	ring Body Inspection	1	Air Conditioning / Heater					
Under Carriag	e and Under Bonne	et Inspection Comn	Operation	/				
4x4/ major unde	er body surface rust		Electrical / Accessories					
				Head lights	V			
				Tail lights	V			
Interior Comn	nents			Indicators	1			
Seats:	Average			Dashboard warning lights	•			
Carpets:	Average			Wipers (front & rear)	•			
Panels:	Average			Window winder FL	•			
Dashboard:	holes in dash		Window winder FR	1				
General Comr	ments		Window winder RL	1				
				Window winder RR	1			
				Rear view mirrors	1			
				Radio (basic test only)	1			
Road Condition	ns During Test Drive	Dry		CD (basic test only)	1			
Engine Timing		Cambelt	Number of keys	2	I			
					1			

I have read and understood this condition guide:

Inspected by:

Published by:

Evidence of Cam Belt Replacement

Inspection Date: 17 Dec 2025

Uriah Pepene

Uriah Pepene

NAME

✓ Yes

No

SIGNATURE

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

1

133,628 Kms