


Report ID:	26,127,349	Version:	2
Created:	17 Mar 2026		

Make:	Volkswagen	Model:	Crafter
Body Style:	Van	Year:	2018
Rego No.:	LKJ137	Rego Expiry:	22 Aug 2026
WoF Expiry:	27 Mar 2027	Odometer:	160,638 Kms
Good No.:	26127349	VIN:	WV1ZZSYZJ9005353
Next Service:	162,000	Service History:	Yes

**Note: This report is not a warranty**  
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**  
 S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Both rear lights cracked. Roof covered in mould

Conditions During Body Inspection	Dry
-----------------------------------	-----

### Under Carriage and Under Bonnet Inspection Comments

Brake warning lights on dashboard ( new pads fitted). Substance that looks like mud that's actually paper like underneath the engine area, potential fire hazard

### Interior Comments

Seats:	driver hole,marks
Carpets:	Average
Panels:	scratches scuffs
Dashboard:	Average

### General Comments

Engine light on. Brake pads warning light on. Add blue warning light on

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No    Kms
Inspected by:	Gary Adams
Published by:	Amanda Loader
Inspection Date:	04 Mar 2026

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance		✓	
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance		✓	
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			8.0 mm
Right front			8.0 mm
Left rear			5.0 mm
Right rear			6.0 mm
Spare		N/A	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights		✓	
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:      **NAME** \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_