

| | | | |
|------------|-------------|----------|---|
| Report ID: | 26,128,446 | Version: | 1 |
| Created: | 30 Mar 2026 | | |


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Skoda | Model: | Superb |
| Body Style: | Wagon | Year: | 2023 |
| Rego No.: | PUK8 | Rego Expiry: | 09 Mar 2027 |
| WoF Expiry: | 25 Mar 2027 | Odometer: | 241,668 Kms |
| Good No.: | 26128446 | VIN: | TMBKD9NP0P7017907 |
| Next Service: | 256,000 Kms | Service History: | Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Front bumper cracked.
 Holes in bumpers and roof for previous police equipment

Conditions During Body Inspection

Dry

Under Carriage and Under Bonnet Inspection Comments

Battery failed.
 Oil approximately 1/2.
 Dipstick faster tag broken

Interior Comments

| | |
|------------|---|
| Seats: | both frt seats split, marks |
| Carpets: | holes police equipment |
| Panels: | scratches scuffs marks |
| Dashboard: | air conditioning vents broken, upper trim missing |

General Comments

Air conditioning and heating systems along with reverse camera view and navigation ok. Start stop has been deactivated by police

Road Conditions During Test Drive Dry

Engine Timing Mechanism Timing Chain

Evidence of Cam Belt Replacement Yes No Kms

Inspected by: Gary Adams

Published by: Amanda Loader

Inspection Date: 30 Mar 2026

| | OK | Requires Attention | N/A |
|---|----|--------------------|--------|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | | | 5.0 mm |
| Right front | | | 5.0 mm |
| Left rear | | | 6.0 mm |
| Right rear | | | 6.0 mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | | | ✓ |
| Number of keys | 2 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | ✓ | | |
| Reversing camera | ✓ | | |

I have read and understood this condition guide:

NAME _____

SIGNATURE _____