


Report ID:	26,129,037	Version:	2
Created:	12 May 2026		

Make:	Nissan	Model:	Navara
Body Style:	Utility	Year:	2019
Rego No.:	MBA243	Rego Expiry:	25 Jun 2026
WoF Expiry:	08 Mar 2027	Odometer:	167,457 Kms
Good No.:	26129037	VIN:	MNTCB2D23A0014349
Next Service:	170,000 Kms	Service History:	Yes

**Note: This report is not a warranty**  
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**  
 S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Front bumper poor fitment.  
 Windscreen has stone chip.  
 Keys for canopy not provided.

Conditions During Body Inspection    Dry

### Under Carriage and Under Bonnet Inspection Comments

Drive belt worn.

### Interior Comments

Seats:	Average
Carpets:	wear in drivers footwell.
Panels:	scuffs.
Dashboard:	scuffs and scratches on glovebox.

### General Comments

1 out of 2 keys remotes nw.  
 Air conditioning and heating systems ok along with reversing camera and sat nav working at time of inspection.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No    Kms
Inspected by:	Finlay Lemmens
Published by:	Amanda Loader
Inspection Date:	24 Apr 2026

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			3.0 mm
Right front			1.0 mm
Left rear			3.0 mm
Right rear			3.0 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys		2	
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)	✓		
Reversing camera	✓		

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_