

Report ID:	26,130,316	Version:	1
Created:	15 Jun 2026		


Make:	Mitsubishi	Model:	Triton
Body Style:	Utility	Year:	2021
Rego No.:	NGL908	Rego Expiry:	20 Feb 2027
WoF Expiry:	21 May 2027	Odometer:	165,138 Kms
Good No.:	26130316	VIN:	MMAWLKL10MH009044
Next Service:	180,000	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Both front tires edges bald, second layer visible on multiple spots other tires. stone chips, dents scuffs, paint defects, rust, cracks, paint defects. Rear number plate frame distorted. Lhs canopy door bent. Driver door check strap missing, front guard Bent. Driver mirror damaged

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Battery passed. Coolant bottle was dry and radiator very low, took at least 2ltrs water

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Air conditioning and heating systems ok. Indicator Rhf hs hole in, Lhf water in. Front bumper poor fit.

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Gary Adams	
Published by:	Amanda Loader	
Inspection Date:	15 Jun 2026	

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition		✓	
Cooling performance		✓	
Radiator / Hoses (visual)		✓	
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			0.0 mm
Right front			0.0 mm
Left rear			2.0 mm
Right rear			3.0 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators		✓	
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____