

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 26,133,339  | Version: | 2 |
| Created:   | 08 Jul 2026 |          |   |


|               |                    |                  |                   |
|---------------|--------------------|------------------|-------------------|
| Make:         | Suzuki             | Model:           | Swift             |
| Body Style:   | Hatchback          | Year:            | 2021              |
| Rego No.:     | NJP327             | Rego Expiry:     | 15 Sep 2026       |
| WoF Expiry:   | 06 Mar 2027        | Odometer:        | 85,229 Kms        |
| Good No.:     | 26133339           | VIN:             | JSAAZC83S00401597 |
| Next Service: | 11/5/27 or 98000km | Service History: | Yes               |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Conditions During Body Inspection Dry

## Under Carriage and Under Bonnet Inspection Comments

## Interior Comments

|            |      |
|------------|------|
| Seats:     | Good |
| Carpets:   | Good |
| Panels:    | Good |
| Dashboard: | Good |

## General Comments

Vehicle drove well.  
key fob not working.

|                                   |                                                              |
|-----------------------------------|--------------------------------------------------------------|
| Road Conditions During Test Drive | Dry                                                          |
| Engine Timing Mechanism           | Timing Chain                                                 |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes <input type="checkbox"/> No Kms |
| Inspected by:                     | Aaron Johnson                                                |
| Published by:                     | Aaron Johnson                                                |
| Inspection Date:                  | 08 Jul 2026                                                  |

OK Requires Attention N/A

## Engine

|                           |   |  |  |
|---------------------------|---|--|--|
| Oil level                 | ✓ |  |  |
| Smoke & fumes             | ✓ |  |  |
| Engine performance        | ✓ |  |  |
| Noise                     | ✓ |  |  |
| Coolant condition         | ✓ |  |  |
| Cooling performance       | ✓ |  |  |
| Radiator / Hoses (visual) | ✓ |  |  |

## Transmission

|                |   |  |   |
|----------------|---|--|---|
| Operation      | ✓ |  |   |
| Noise          | ✓ |  |   |
| Clutch         |   |  | ✓ |
| CV joints      | ✓ |  |   |
| Wheel bearings | ✓ |  |   |

## Brakes

|             |   |  |  |
|-------------|---|--|--|
| Performance | ✓ |  |  |
| Hand brake  | ✓ |  |  |

## Tyres (lowest observed tread depth of tyres)

|             |      |
|-------------|------|
| Left front  | 6 mm |
| Right front | 6 mm |
| Left rear   | 6 mm |
| Right rear  | 6 mm |
| Spare       | Yes  |

## Suspension

|                        |   |  |  |
|------------------------|---|--|--|
| Suspension performance | ✓ |  |  |
| Steering performance   | ✓ |  |  |
| Shock absorbers        | ✓ |  |  |

## Air Conditioning / Heater

|           |   |  |  |
|-----------|---|--|--|
| Operation | ✓ |  |  |
|-----------|---|--|--|

## Electrical / Accessories

|                             |   |   |   |
|-----------------------------|---|---|---|
| Head lights                 | ✓ |   |   |
| Tail lights                 | ✓ |   |   |
| Indicators                  | ✓ |   |   |
| Dashboard warning lights    | ✓ |   |   |
| Wipers (front & rear)       | ✓ |   |   |
| Window winder FL            | ✓ |   |   |
| Window winder FR            | ✓ |   |   |
| Window winder RL            | ✓ |   |   |
| Window winder RR            | ✓ |   |   |
| Rear view mirrors           | ✓ |   |   |
| Radio (basic test only)     | ✓ |   |   |
| CD (basic test only)        |   |   | ✓ |
| Number of keys              | 1 |   |   |
| Central locking             | ✓ |   |   |
| Remote locking              |   | ✓ |   |
| Sat. nav. (basic test only) | ✓ |   |   |
| Reversing camera            | ✓ |   |   |

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_