

Basic Vehicle Condition Guide

Report ID: 26,277,856

Version: 1

Created: 18 Sep 2024


Make:ToyotaModel:AquaBody Style:Year:2019Registration:Reg Expiry:

 WoF Expiry:
 17 Sep 2025
 Odometer:
 106,196 Kms
 Good No:
 26277856

 VIN:
 Next Service:
 116193 kms
 Service History:
 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

FWD

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Eleoit Kumar Date: 18 Sep 2024

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	v		
Radiator / Hoses (visual)	~		
Transmission			1
Operation	~		
Noise	~		
Clutch			\ <u>\</u>
CV joints	~		
Wheel bearings	v		
Brakes	•		
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	 es)
Left front	· ·	5	mm
Right front	5		mm
Left rear	6		mm
Right rear	6		mm
Spare	Yes		
Suspension			
Suspension performance	V		Ι
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	l	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			'
Reversing camera	~		
	1	1	

Signature: