

Report ID: 26,295,262 3 Version: 29 Dec 2024 Created:

Make:	Volkswagen	Model:	Polo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	Registration:	JZF687	Reg Expiry:	25 Mar 2025	Engine	1	<u> </u>	L
WoF Expiry:	25 Sep 2025	Odometer:	84,288 Kms	Good No:	26295262	Oil level	~		
VIN:	WVWZZZ6RZDU045574	Next Service:	94,000	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	iical inspection prior to	purchase and t	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	SC S	M/	P SC S D SC V	W Sw	SC	Performance	V		
Key:	30 [3	<u> </u>	F 3C 3D 3C			Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust PT = paint defect C = crack SW PSC						Operation	V		
						Noise	V		
						Clutch			~
P = pin dent	Inco HIC				74 <u>11</u> 4	CV joints	r		
* = decals						Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs S D W S W S D SC W S PT SC W S P W						Performance	~		
Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread			1 2S)
						Left front 8.0			
						Right front		.0	mm
						Left rear	6		mm
Conditions During Body Inspection: Dry						Right rear		.0	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front wheel drive.						Suspension performance	~		
Front whee	drive,					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		I
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ord Good					Window winder FL	~		
	I				J	Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	V		
						Radio (basic test only)	V		
						CD (basic test only)	V		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			V
LI									
Inspected by: Andre Richardson Date: 09 Sep 2024									
I have read and understood this condition guide. Name:									