

Report ID: 26,315,107 Version: 2 10 Oct 2024 Created:

Make:	Subaru	Model:	XV	Body Style:			Pass	Fail	N/A	
Year:	2013	<b>Registration:</b>		Reg Expiry:		Engine	•		·	
WoF Expiry:	02 Oct 2025	Odometer:	76,452 Kms	Good No:	26315107	Oil level	~			
VIN:		Next Service:	86,449kms	Service History	: Yes	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
						Performance	~			
Key:		-0				Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust						Operation	~			
PT = paint def				$\left[ \left( \right) \right]$		Noise	~			
C = crack					╫╫╫────	Clutch			~	
P = pin dent	HIS			$ \rangle$	4111	CV joints	~			
* = decals	- Alt			TO		Wheel bearings	~			
SC = stone chips						Brakes	Brakes			
W = significant scuffs						Performance	~			
Dealertee	<u> </u>	Note: som	ne defects & blemishes	may not be displa	ayed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			25)	
						Left front 8.0 r				
						Right front		.0	mm	
						Left rear		.0	mm	
Conditions During Body Inspection: Dry						Right rear		.0	mm	
Conditions During Body Inspection: Dry						Spare N/A				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
All wheel d	rive.					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~		<u> </u>	
						Air Conditioning / Heater				
						Operation				
Interior Comments						Electrical / Accessories				
Seats Good						Head lights	~			
	Card					Tail lights	~			
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
						Wipers (front & rear)	~		$\left  - \right $	
Dashboa	rd Good					Window winder FL	~		$\left  - \right $	
						Window winder FR	~		<u> </u>	
General Comments						Window winder RL	~			
						Window winder RR	~		<u> </u>	
						Rear view mirrors	~		$\left  - \right $	
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2		1	
Road Conditions During Test Drive: Dry						Central locking				
Road Conditions During Test Drive: Dry						Remote locking	~		$\left  - \right $	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		-	
[	-						-	1		
Inspected by: Takaya Murayama Date: 04 Oct 2024										

I have read and understood this condition guide.

Name: .....

Signature: .....