

Report ID: 26,353,674 4 Version: 31 Jan 2025 Created:

Make:	Mazda	Model:	Axela	Body Style:	Sedan		Pass	Fail	N/A
Year:	2014	<b>Registration:</b>		Reg Expiry:		Engine	1		L
WoF Expiry:	23 Dec 2025	Odometer:	68,284 Kms	Good No:	26353674	Oil level	~		
VIN:	7AT0C13JX24106499	Next Service:	78,000 Kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and ti	his can be arranged to	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:				5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s AR			20		Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	HE				2416	CV joints	~		
* = decals	- dle	10		10	ED S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
, significan		C				Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Tyre repair kit as opposed to spare wheel.						Left front	6.	.0	mm
						Right front	6.	.0	mm
						Left rear	6.	.0	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	ird Good					Wipers (front & rear)	~		
						Window winder FL	~		
Concret	Commonto					Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		-
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Troy Smith Date: 14 Jan 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....