

Basic Vehicle Condition Guide

Report ID: 26,364,208


Version: 1

Created: 15 Oct 2024

Make: Model: Holden Colorado **Body Style:** Utility Year: 2013 Registration: NMZ998 Reg Expiry: 05 Aug 2024 WoF Expiry: **Odometer: Good No:** 05 Dec 2024 171,172 Kms 26364208 VIN: MMU142MH0DH6701 Next Service: 0 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Nudge bar after market front bumper, snorkel RF guard, modified RF guard,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Minor oil leak,

Interior Comments	<u>S</u>
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Drives okay needs a service,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

Inspected by:	Donovan Matara	Date:	15 Oct 2024
---------------	----------------	-------	-------------

Name:

	d: 15	Oct 2	024
	Pass	Fail	N/A
Engine	I	<u> </u>	1
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	V		
Transmission	ı		1
Operation	~		
Noise	\(\times \)		
Clutch	~		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	6	.5	mm
Right front	6	.5	mm
Left rear	5	.0	mm
Right rear	5.2		mm
Spare		Yes	
Suspension	•		
Suspension performance	~		
Steering performance	<i>v</i>		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		~	
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Indicators Dashboard warning lights	V		
	VVV		
Dashboard warning lights	\(\times \)		
Dashboard warning lights Wipers (front & rear)			
Dashboard warning lights Wipers (front & rear) Window winder FL			V
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR			V
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL			\(\times \)
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR			<i>V V V</i>
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors			\(\nu \)
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only)			<i>V V V V</i>
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	V V V		\(\sigma\)
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	V V V		\(\nu \)
Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	V V V		\(\bullet \cdot \c

Signature: