

Report ID: 26,423,534 1 Version: 22 Jan 2025 Created:

Make:	Subaru	Model:	XV	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2013	Registration:		Reg Expiry:		Engine			L	
WoF Expiry:		Odometer:	99,133 Kms	Good No:	26423534	Oil level	~			
VIN:	7AT0GF1XX24043740	Next Service:	109108	Service Histor	y: No	Smoke & fumes	~		<u> </u>	
						Performance	~			
	port is not a warranty	oration is made	for ago and milaago	Darte have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
						Performance	~			
Key:		-0		-01-		Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
D = dent R = rust				715	E SP	Operation	~			
PT = paint defe		r I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HID				2414	CV joints	~			
* = decals	- Alt					Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
						Performance	~			
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)				
						Left front	5.0 mm			
						Right front	5.	0	mm	
						Left rear	5.	0	mm	
Conditions During Body Inspection: Dry						Right rear	6.0 mm		mm	
						Spare	N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	11		L	
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
						Tail lights	~			
Carpets	Average					Indicators	~			
Panels	Good					Dashboard warning lights	~			
						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	~			
General Comments					Window winder RL	~				
.						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected	Inspected by: Chris Buckley Date: 22 Jan 2025									

I have read and understood this condition guide.

Name:

Signature: