

Report ID: 26,447,950 1 Version: 14 Jan 2025 Created:

Make:	Toyota	Model:	Aqua	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>		<b>Reg Expiry:</b>		Engine		·	
WoF Expiry:	09 Jan 2026	Odometer:	35,551 Kms	Good No:	26447950	Oil level	~		
VIN:	7AT0H65YX25240932	Next Service:	45,000 kms	Service Histor	r <b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection phor to	purchase and t	lis can be arranged ic		charge.	Coolant condition	~		
						Performance	~		
<b>Key:</b> S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust				10		Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack				TTY,		Clutch			~
P = pin dent	HIP				2416	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	6	.5	mm
						Right front	6	.5	mm
						Left rear	7	7	mm
Conditions During Body Inspection: Dry						Right rear	7.5 mm		
						Spare N/A			
Under Ca	rriage & Under Bor	net Inspectio	on Comments			Suspension	-		
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
lusterier C						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
Concert						Window winder FR	~		<u> </u>
	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Enging Ti	ming Machanism	Timeline	Chain			Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected	d by: Dean Sinclair					Date: 14 Jan 202	25		
Inspected	a sy					Dute	-		

I have read and understood this condition guide.

Name: .....

Signature: .....