

## **Basic Vehicle Condition Guide**

Report ID: 26,448,051


Version:

15 Jan 2025 Created:

Make: Subaru Model: Legacy **Body Style:** Wagon Year: 2012 Registration: **Reg Expiry:** WoF Expiry: **Odometer:** 13 Jan 2026 114,297 Kms **Good No:** 26448051 VIN: 7AT0GF0BX25005276 **Next Service:** 124,000 kms **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>	
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

**General Comments** 

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism:** Timing Chain

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Dean Sinclair Inspected by:

Fail N/A Pass Engine Oil level Smoke & fumes 1 Performance / Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front 6 mm Left rear 6.5 mm Right rear 6.5 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 2 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera

I have read and understood this condition guide.

Name: .....

Signature: .....

15 Jan 2025

Date: