

Report ID: 26,459,323 Version: 1 02 Dec 2024 Created:

Signature:

Make:	Toyota	Model:	Landcruiser	Body Style:	SUV		Pass	Fail	N/A
Year:	2001		ADU943	Reg Expiry:	17 Jun 2025	Engine			<u> </u>
WoF Expiry:		Odometer:	529,708 Kms	Good No:	26459323	Oil level	~		
VIN:	JTEHC05J604005008	Next Service:		Service Histor		Smoke & fumes	~		
	512		52 .,000			Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	SDW	-0	SW SPTCV	<u>v</u> al	DW	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation			
R = rust				10			-		
PT = paint def C = crack	ect N			$ \cup$	PT	Noise Clutch	~		
P = pin dent	Ht	KI							~
* = decals	S PT SC W D			SI	EN SPW	CV joints		~	
SC = stone chips						Wheel bearings			
W = significant scuffs S D SC W S D S D S D S D						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Windscreen stone chips / crack						Tyres (lowest observed tread depth of tyres)			
Headlight cracked						Left front	7 mm		
						Right front	3	3	mm
					Left rear	5 mm		mm	
Conditions During Body Inspection: Dry						Right rear	5 mm		
					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Both side inner & outer cv boots leaking grease Underbody surface rust						Suspension performance	~		
Engine & transmission oil seep						Steering performance	~		
4 wheel drive						Shock absorbers	~		
						Air Conditioning / Heater	-		
	_					Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights		~	
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
<u>General C</u>	<u>Comments</u>					Window winder RL	~		
·						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	I	L
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 465,069						Reversing camera			~
L						<u> </u>	1		
Inspected by: Rowan Fey Date: 02 Dec 2024									

I have read and understood this condition guide.

Name: