

Report ID: 26,464,143 5 Version: 21 Jan 2025 Created:

| Make: | Toyota | Model: | Aqua | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|---|----------------|-------------------------|-------------------|--------------------------|--|--------|--------|----------|
| Year: | 2015 | Registration: | | Reg Expiry: | | Engine | | | L |
| WoF Expiry: | | Odometer: | 102,808 Kms | Good No: | 26464143 | Oil level | ~ | | |
| VIN: | 7AT0H65YX24394757 | | | Service Histor | | Smoke & fumes | ~ | | |
| | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | | 112,007 Kills | | . 165 | Performance | ~ | | |
| | port is not a warranty | | | | | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | STO | A CO | | | T | Transmission | v | | |
| D = dent | GIR | | | 1n- | | Operation | ~ | | |
| R = rust | | | | 10 | JHIL | Noise | ~ | | |
| PT = paint def C = crack | | | | + | | Clutch | • | | ~ |
| P = pin dent | Ho | | | | | CV joints | ~ | | |
| * = decals | - MIK | | | AL. | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs | | | | | | Performance | ~ | | <u> </u> |
| | | Note: son | ne defects & blemishes | may not be disr | laved in the diagram | Hand Brake | ~ | | |
| Body Insp | pection Comments | Note: 3011 | le delects à blemistie. | s may not be disp | ayea in the diagram | | - | oftyre | |
| | | | | | | Tyres (lowest observed tread depth of tyres) Left front 7.0 mm | | | |
| | | | | | | | | | mm |
| | | | | | | Right front Left rear | 7. | | mm |
| | | | | | | | 7. | - | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 7.0 mm | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | |
| | inage a onder bor | ince inspectie | <u>Comments</u> | | | Suspension | | | <u> </u> |
| Front whee | l drive. | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | <u> </u> |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | <u> </u> |
| Interior Comments | | | | | | Operation 🖌 | | | |
| | | | | | Electrical / Accessories | | | | |
| Seats | Good | | | | | Head lights | ~ | | - |
| Carpets | Good | | | | | Tail lights | ~ | | |
| | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Good | | | | | Wipers (front & rear) | ~ | | |
| | | | | | | Window winder FL | ~ | | |
| General | <u>Comments</u> | | | | | Window winder FR | ~ | | |
| | <u>comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | <u> </u> |
| Engine Timing Mechanism: Timing Chain | | | | | | Remote locking | ~ | | |
| | | | | | | Sat. Nav. (basic test only) | | | ~ |
| | | chient. N | lot Applicable | 11115. | | Reversing camera | ~ | | |
| Inspected by: Takaya Murayama Date: 20 Dec 2024 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: