

7AT0H63EX24189744

Basic Vehicle Condition Guide

Report ID: 26,464,330

2 Version:

09 Jan 2025 Created:

Make: Model: Toyota Vitz **Body Style:** Hatchback

Year: 2014 WoF Expiry: 20 Dec 2025

VIN:

Registration: **Odometer:**

Next Service:

Reg Expiry:

17,678 Kms


27676 kms

Good No: 26464330

Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Fwd

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

20 Dec 2024 Marlon Espena Inspected by: Date:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	<i>V V</i>		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			1
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	7	.0	mm
Right front	7.0		mm
Left rear	7	.0	mm
Right rear	7.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	<u> </u>		ļ
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	V V V		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	<u> </u>		~
Number of keys	2		<u> </u>
Central locking	<u> </u>		
Remote locking	1		
Sat. Nav. (basic test only)	Ť		~
Reversing camera	~		

I have read and understood this condition guide.

Name:

Signature: