

Report ID: 26,474,172 3 Version: 13 May 2025 Created:

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2015	<b>Registration:</b>	HZM368	<b>Reg Expiry:</b>	19 Sep 2025	Engine			
WoF Expiry:	09 Jul 2025	Odometer:	193,838 Kms	Good No:	26474172	Oil level	~		
VIN:	KMHSU81XSFU390696	Next Service:	201,000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	a Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
						Coolant condition	~		
	SC					Performance	~		
Key:		-0		501-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SSC						Operation	~		
PT = paint defect						Noise	~		
C = crack				+1		Clutch			~
P = pin dent	HIS				7414	CV joints	~		
* = decals SD 999						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Body Incr	action Commonts	Note: som	ne defects & blemishe	es may not be disp	blayed in the diagram	Hand Brake	~		
	pection Comments	2				Tyres (lowest observed tread	l d depth	of tyre	es)
Rear badge broken - clear coat on bonnet peeling.						Left front 6.0 mm			mm
						Right front	6		mm
						Left rear	6	.0	mm
Conditions During Body Inspection: Dry						Right rear			mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Runs on diesel fuel. Vehicle has belly pans. Tested battery and passed.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
L						Operation	~		
Interior Comments						Electrical / Accessories			1
Seats Average					Head lights	~			
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	I					Window winder FR	~	-	
General Comments					Window winder RL	~			
Air conditioning and heating systems along with reverse camera and navigation work at inspection					Window winder RR	~			
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	1	I
Road Conditions During Test Drive: Dry						Central locking	~		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
									1
Inspected by: Gary Adams Date: 11 Dec 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....