

Report ID: 26,498,611 3 Version: 15 May 2025 Created:

Make:	Citroen	Model:	C4 Grand Picasso	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2016	Registration:	QWY694	Reg Expiry:	12 Jun 2025	Engine			<u> </u>
	11 Mar 2026	Odometer:	105,082 Kms	Good No:	26498611	Oil level	~		
VIN:	VF73AAHXTEJ592319	Next Service:	113,000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	nical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		1
						Performance	~		
Key:	S	-0	DD	-161-	S D	Radiator / Hoses (visual)	~		+
S = scratch						Transmission			
D = dent S PT SC D C						Operation	~		<u> </u>
R = rust PT = paint defe	act The			\prod	JUIL	Noise	~		+
C = crack				$+ \mathbf{\nabla}$		Clutch			~
P = pin dent	H				세비	CV joints	~		+
* = decals	ssc 916		K	- NL		Wheel bearings	~		+
SC = stone chips						Brakes	•		
W = significant scuffs						Performance	~		1
		Note: sor	ne defects & blemishe	s may not be disc	layed in the diagram	Hand Brake	~		+
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed treat	· ·	of tvr4	L es)
Stone chips in front screen.									
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Rody Inspection:						Right rear			
Conditions During Body Inspection: Dry						Spare	5.0 mm Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
Vehicle has	s belly pans. No jack eq	uipment found ir	n vehicle.			Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
		Operation	~		1				
Interior Comments						Electrical / Accessories	•		<u> </u>
Seats	Average					Head lights	~		1
Jeats	Avelage					Tail lights	~		+
Carpets	Average					Indicators	~		
Panels	A					Dashboard warning lights	~		
ranels	Average					Wipers (front & rear)	~		
Dashboa	ard Average					Window winder FL	~		
	I					Window winder FR	~		+
General Comments						Window winder RL	~		+
						Window winder RR	~		+
Air conditioning temperature good and heating also. 1 remote not working. Please note that this vehicle has mold inside and has a potential water leak .						Rear view mirrors	~		+
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Decil		4 Duits				Central locking	2 V		1
Road Conditions During Test Drive: Dry						Remote locking	-		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	v		
Evidence of Cam Belt Replacement: Not Applicable Kms:							v		
						Reversing camera	~		
Inspecte	d by: Gary Adams					Date: 24 Dec 20	24		
have read	and understood th	is condition o	uide. Name:			Signature:			