

Basic Vehicle Condition Guide

Report ID: 26,522,156

Version: 2

Created: 05 Feb 2025


Make:ToyotaModel:C-HRBody Style:Year:2017Registration:Reg Expiry:

 WoF Expiry:
 04 Feb 2025
 Odometer:
 83,927 Kms
 Good No:
 26522156

 VIN:
 Next Service:
 93,924 kms
 Service History:
 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Fwd

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Marlon Espena Date: 05 Feb 2025

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	<i>v</i>		
Noise	~		
Cooling System	•		
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		4	mm
Right front		4	mm
Left rear	4		mm
Right rear		4	mm
Spare		N/A	
Suspension			1
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories	1		
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors			
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	'		

Signature: