

## **Basic Vehicle Condition Guide**

Report ID: 26,522,333

Version:

03 Feb 2025 Created:

Make: Model: Mazda Mazda3 **Body Style:** Hatchback

Year: 2019 WoF Expiry: 28 Jan 2026

Registration:


**Odometer:** 70,195 Kms **Good No:** 26522333

VIN: 7AT0C13GX25105330 Next Service: 80,100 kms **Service History:** 

Reg Expiry:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Note: some defects & blemishes may not be displayed in the diagram

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Fwd

| Interior Comments |      |  |  |  |
|-------------------|------|--|--|--|
| Seats             | Good |  |  |  |
| Carpets           | Good |  |  |  |
| Panels            | Good |  |  |  |
| Dashboard         | Good |  |  |  |

| General Commen | tc. |
|----------------|-----|

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Timing Chain

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Marlon Espena Inspected by:

|                              | Pass                                   | Fail    | N/A  |
|------------------------------|--|---------|------|
| Engino                       | F 033                                  | 1 all   | IN/A |
| Engine Oil level             | .,                                     |         |      |
| Smoke & fumes                | •                                      |         |      |
|                              | \( \times \)                           |         |      |
| Performance                  | •                                      |         |      |
| Noise                        | •                                      |         |      |
| Cooling System               |  |         |      |
| Coolant condition            | •                                      |         |      |
|                              | rerformance  Addiator / Hoses (visual) |         |      |
| Radiator / Hoses (visual)    | <b>/</b>                               |         |      |
| Transmission                 | ı                                      | 1       |      |
| Operation                    | ~                                      |         |      |
| Noise                        | ~                                      |         |      |
| Clutch                       |  |         | ~    |
| CV joints                    | ~                                      |         |      |
| Wheel bearings               | ~                                      |         |      |
| Brakes                       |  |         |      |
| Performance                  | ~                                      |         |      |
| Hand Brake                   | ~                                      |         |      |
| Tyres (lowest observed tread | d depth                                | of tyre | es)  |
| Left front                   | 5.5                                    |         | mm   |
| Right front                  | 5.5                                    |         | mm   |
| Left rear                    | 6.0                                    |         | mm   |
| Right rear                   | 6.0                                    |         | mm   |
| Spare                        | N/A                                    |         |      |
| Suspension                   | •                                      |         |      |
| Suspension performance       | ~                                      |         |      |
| Steering performance         | ~                                      |         |      |
| Shock absorbers              | ~                                      |         |      |
| Air Conditioning / Heater    | ı                                      |         | 1    |
| Operation                    | ~                                      |         |      |
| Electrical / Accessories     |  | l .     | 1    |
| Head lights                  | ~                                      |         |      |
| Tail lights                  | ~                                      |         |      |
| Indicators                   | ~                                      |         |      |
| Dashboard warning lights     | \( \times \)                           |         |      |
| Wipers (front & rear)        | ~                                      |         |      |
| Window winder FL             | <i>v</i>                               |         |      |
| Window winder FR             | ~                                      |         |      |
| Window winder RL             | ~                                      |         |      |
|                              | Ι.                                     | 1       | 1    |

Window winder RR Rear view mirrors Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Date:

~

/

2

30 Jan 2025

~

I have read and understood this condition guide. Name: ..... Signature: .....