

Basic Vehicle Condition Guide

Report ID: 26,526,561


Version:

Created: 03 Feb 2025

Make: Model: Volvo C30 **Body Style:** Hatchback Year: 2010 Registration: PEF811 Reg Expiry: 27 Feb 2025 WoF Expiry: **Odometer:** 09 Sep 2025 72,334 Kms **Good No:** 26526561 VIN: YV1MK755BA2197404 **Next Service:** 82000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	driver split		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: No.

No

Kms:

Inspected by: Gary Adams Date: 14 Jan 2025

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	•	
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	6	.0	mm
Right front	6	.0	mm
Left rear	6	.0	mm
Right rear	6.0		mm
Spare		N/A	
Suspension			
Suspension performance	~		
Steering performance	<i>'</i>		
Shock absorbers	~		
Air Conditioning / Heater			l
Operation	~		
Electrical / Accessories			
Head lights	V		
Tail lights	~		
Indicators	<i>y</i>		
Dashboard warning lights	~		
Wipers (front & rear)	\(\times \)		
Window winder FL	<i>v</i>		
Window winder FR	<i>y</i>		
Window winder RL			
Window winder RR			1
Rear view mirrors	.,		
	•		
Radio (basic test only)	•		
CD (basic test only)	1		
Number of keys	1		1
Central locking	•		
Remote locking			
Sat. Nav. (basic test only)			'
Reversing camera	<u> </u>	<u> </u>	

Signature: