

Basic Vehicle Condition Guide

Report ID: 26,532,961


Version: 4

Created: 12 Feb 2025

Make: Model: Mercedes-Benz E350 **Body Style:** Sedan Year: 2009 Registration: JCU798 Reg Expiry: 18 May 2025 **WoF Expiry: Odometer:** 15 Nov 2025 110,780 Kms **Good No:** 26532961 VIN: WDD2073562F024801 Next Service: 115,000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Clear coat coming Rf guard

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

front shocks signs of age oil weeps . Runs on 95 octane fuel. Vehicle has belly pans

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

General Comments

Driver mirror doesn't adjust properly. Air conditioning and heating system along with reverse camera and navigation ok. Radio screen has black line across the lower portion

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Gary Adams Date: 16 Jan 2025

Name:

	- Create					
		Pass	Fail	N/A		
	Engine		1			
	Oil level	~				
	Smoke & fumes	\(\times \)				
	Performance	~				
	Noise	~				
	Cooling System					
	Coolant condition	~				
	Performance	~				
	Radiator / Hoses (visual)					
	Transmission					
	Operation	~				
	Noise	~				
	Clutch			~		
	CV joints			~		
	Wheel bearings	~				
	Brakes					
	Performance	~				
	Hand Brake	~				
	Tyres (lowest observed tread depth of tyres)					
	Left front	7.0		mm		
	Right front	7.0		mm		
	Left rear	6.0 r		mm		
	Right rear	6.0 m		mm		
	Spare	Yes				
	Suspension					
	Suspension performance	~				
	Steering performance	~				
	Shock absorbers	~				
	Air Conditioning / Heater					
Operation 🗸						
Electrical / Accessories						
	Head lights	~				
	Tail lights	~				
	Indicators	~				
	Dashboard warning lights	~				
	Wipers (front & rear)	~				
	Window winder FL	~				
	Window winder FR	~				
	Window winder RL	~				
	Window winder RR	~				
	Rear view mirrors		~			
	Radio (basic test only)		~			
	CD (basic test only)	~				
	Number of keys	2	I	-		
	Central locking	·				
	Remote locking	~				
	Sat. Nav. (basic test only)	~				
1	Reversing camera	~				
	eversing cumera					

Signature: