

Report ID: 26,544,300 3 Version: 11 May 2025 Created:

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2016	Registration:	JPS195	<b>Reg Expiry:</b>	25 Jul 2025	Engine			
WoF Expiry:	26 Jul 2025	Odometer:	221,147 Kms	Good No:	26544300	Oil level	V		
VIN:	KMHST81XSGU594669	Next Service:	16/10/25	Service Histor	<b>y:</b> Yes	Smoke & fumes	V		
						Performance	V		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	S S			Radiator / Hoses (visual)	V		
S = scratch D = dent R = rust						Transmission			
						Operation	~		
PT = paint defe				$\left[ \left( \right) \right]$		Noise	r		
C = crack						Clutch			~
P = pin dent	sc dle				74114	CV joints	~		
* = decals				Tool .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan	S		S S		S	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
					Left front	t front 5.0 mr			
Right front							5.0 mm		mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Dry Right rear							5	.0	mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
1						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
CD (basic test only)									
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking									
Remote locking							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: My Auto Shop Date: 23 Jan 2025									

I have read and understood this condition guide.

Name: .....