

## **Basic Vehicle Condition Guide**

Report ID: 26,548,792


Version:

01 Feb 2025 Created:

Make: Model: Subaru ΧV **Body Style:** Wagon Year: 2014 Registration: PKE142 Reg Expiry: 07 Feb 2025 **Odometer:** WoF Expiry: 06 Jan 2026 120,428 Kms **Good No:** 26548792 VIN: 7AT0GF1XX22019860 Next Service: 130000 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Minor stone chips on windscreen

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

All wheel drive

<u>Interior Comments</u>		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Timing Chain

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Jaykib Collins

Pass	Fail	N/A		
~				
>				
~				
/				
~				
<b>'</b>				
~				
~				
~				
		~		
~				
~				
~				
· · · ·		Ļ		
Tyres (lowest observed tread depth of tyres)  Left front 6.0 mm				
		mm		
-		mm		
		mm		
3		mm		
Spare No Suspension				
•				
·/				
Shock absorbers  Air Conditioning / Heater				
Electrical / Accessories				
~				
~				
~				
~				
~				
~				
~				
~				
~				
~				
~				
•	1	1		
~				
~				
~				
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ		

I have read and understood this condition guide.

Name: .....

Signature: .....

22 Jan 2025

Reversing camera