

Report ID: 26,548,825 6 Version: 17 May 2025 Created:

Make:	Mitsubishi	Model:	Pajero	Body Style:	Wagon		Pass	Fail	N/A
Year:	2007	Registration:	НКВ628	Reg Expiry:	01 Apr 2025	Engine			
WoF Expiry:		Odometer:	186,918 Kms	Good No:	26548825	Oil level	~		
VIN:	7AT0CJ08X13002009	Next Service:		Service Histor		Smoke & fumes	~		
					,	Performance	~		
Note: This report is not a warranty						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	S	-0	ls ls		S	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation			
R = rust				10		Noise	~ ~		
PT = paint defect C = crack						Clutch	~		
P=pin dent									~
* = decals	sc dr				ELLA S	CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs S S S S S						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	<b>~</b>		Ļ
						Tyres (lowest observed tread depth of tyres)			
						Left front	3.8 mm		mm
						Right front	5.	.1	mm
						Left rear	3.		mm
Conditions During Body Inspection: Dry						Right rear	4.7 mn		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Slight wea	Slight wear on drivers seat					~		
Comoto						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Vehicle had trouble starting while on hoist, advise to have checked						Window winder RR	~		
Overheating issue - but has had a compression test and not a head gasket - suspect blocked pipes						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	2					Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	′es	Kms: 14	18,336	Reversing camera	~		
						_			I
Inspected by: Hoani Saunders Date: 16 May 2025									
I have read	and understood th	is condition o	juide. Name:			Signature:			