

Report ID: 26,548,943 2 Version: 21 Mar 2025 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2014	<b>Registration:</b>		<b>Reg Expiry:</b>		Engine		L	
WoF Expiry:	18 Mar 2026	Odometer:	129,448 Kms	Good No:	26548943	Oil level	~		
VIN:	7AT0C13JX25108727	Next Service:	139,444	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust						Operation 🖌			
PT = paint defe				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIS				7414	CV joints	~		
* = decals	- Alt			-No-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Deduction		Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	depth	of tyre	es)
									mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Pody Inspection:						Right rear			mm
Conditions During Body Inspection: Dry						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	V		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Average						Head lights	~		
	Avelage					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	A					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
Tyre repair kit instead of spare wheel.						Window winder RR	~		
Tyre repair	kit instead of spare whe					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking			
Koad Con	aitions During Tes	t Drive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
									•
Inspected by: Lewis Dolamore Date: 20 Mar 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....