

Report ID: 26,553,976 2 Version: 03 Feb 2025 Created:

| Make: | Mini | Model: | Hatch | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|--------------------------|----------------------|------------------------|-------------------|----------------------|--|--------|------|-----|
| Year: | 2017 | Registration: | KHK951 | Reg Expiry: | 24 Jan 2025 | Engine | | | |
| WoF Expiry: | 12 Feb 2026 | Odometer: | 101,516 Kms | Good No: | 26553976 | Oil level | ~ | | |
| VIN: | WMWXM720702A77915 | Next Service: | 111500 | Service History | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | oration is made | for age and mileage | Parts have not | been dismontled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | his can be arranged fo | r an additional c | harge. | Coolant condition | ~ | | |
| | | | SC | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| R = rust | SC DIA | | | 210 | HIV_ | Operation | ~ | | |
| PT = paint defe | ect NP | | | | 17111 | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | *sc dl | | | | 24116 | CV joints | ~ | | |
| *= decais | | | | | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| w – signincan | | | | | | Performance | ~ | | |
| Body Insr | pection Comments | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| body inspection comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | Left front | 6.0 mm | | mm | |
| | | | | | | Right front | 6. | 0 | mm |
| | | | | | | Left rear | 5. | 0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 5.0 mm | | mm |
| | | | | | | Spare | N/A | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | < | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Carpets | Cood | | | | | Tail lights | ~ | | |
| | Good | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd C | | | | | Wipers (front & rear) | ~ | | |
| | rd Good | | | | | Window winder FL | ~ | | |
| Canada | | | | | | Window winder FR | ~ | | |
| <u>General Comments</u> | | | | | | Window winder RL | | | ~ |
| | | | | | | Window winder RR | | | ~ |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| Engine Ti | ming Mechanism | Timina | - hain | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Sat. Nav. (basic test only) | ~ | | |
| Evidence | | ement: N | lot Applicable | NI115. | | Reversing camera | ~ | | |
| Inspected by: Gary Adams Date: 28 Jan 2025 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: