

Report ID: 26,557,910 2 Version: 05 Jun 2025 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass I	ail N/A
Year:	2016	Registration:	JRG29	Reg Expiry:	22 Mar 2025	Engine		
	18 Jan 2026	Odometer:	101,695 Kms	Good No:	26557910	Oil level	~	
VIN:	MMAJJKK10GH022048	Next Service:		Service Histor		Smoke & fumes	~	
						Performance	~	
	port is not a warranty					Noise	~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition		
		_				Performance	~	
Key:		-0				Radiator / Hoses (visual)	~	
S = scratch						Transmission		
D = dent	ISSC AL			1n-		Operation	~	
R = rust				10	JHH	Noise	~	
PT = paint def C = crack				+		Clutch	~	
P = pin dent	Htc					CV joints		~
* = decals	SRSC 91			AL-	SDSC	Wheel bearings	~	
SC = stone chips						Brakes		
W = significant scuffs S SC S D SC S D SC S D SC S D SC						Performance		
		Noto: com				Hand Brake	~	
Body Insp	pection Comments		ne defects & blemishes	may not be disp	layed in the diagram			(to use a)
Front grill damaged. Sunglasses holder broken. No jack equipment					Tyres (lowest observed tread depth of tyres)			
						Left front	6.0	mm
						Right front	6.0	mm
						Left rear	5.0	mm
Conditions During Body Inspection: Dry					Right rear 5.0 mm			
Under Carriage & Under Pennet Inspection Comments					Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension	<u> </u>	
Runs on die	sel fuel.					Suspension performance	~	
						Steering performance	~	
						Shock absorbers	~	
						Air Conditioning / Heater		
Interior Commonte						Operation 🖌		
Interior Comments						Electrical / Accessories		
Seats	marks					Head lights	~	
Carpets	Average					Tail lights	~	
	Average					Indicators	~	
Panels	scratches					Dashboard warning lights	~	
Dashboa	rd					Wipers (front & rear)	~	
Dashboa	rd scratches					Window winder FL	~	
						Window winder FR	~	
<u>General Comments</u>					Window winder RL	~		
Air conditioning and heating systems good temperature along with reverse camera work at inspection time						Window winder RR	~	
						Rear view mirrors	~	
						Radio (basic test only)	~	
						CD (basic test only)	~	
						Number of keys	1	
Road Conditions During Test Drive: Dry						Central locking	~	
						Remote locking	~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)		~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~	
							· · · ·	
Inspected by: Gary Adams Date: 29 Jan 2025								

Name: