

Basic Vehicle Condition Guide

Report ID: 26,560,468


Version:

Created: 07 Feb 2025

Make: Model: Nissan **Dualis Body Style:** Wagon Year: 2007 Registration: QZD217 Reg Expiry: 09 Jan 2026 WoF Expiry: **Odometer:** 24 Sep 2025 190,474 Kms **Good No:** 26560468 VIN: 7AT0DH7HX14018094 Next Service: 197,000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Stone chips in front screen. Parcel tray pin snapped

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

General Comments

Only one remote work.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Gary Adams Date: 30 Jan 2025

Name:

| | Pass | Fail | N/A |
|------------------------------|----------------------------|---------|-----|
| Engine | • | • | • |
| Oil level | ~ | | |
| Smoke & fumes | v | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | • | |
| Coolant condition | ~ | | |
| Performance | <i>V</i> | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 3 | .0 | mm |
| Right front | 3 | .0 | mm |
| Left rear | 6.0 | | mm |
| Right rear | 6.0 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | V V V V V V | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | ~ | | |
| | | | |

Signature: