

Basic Vehicle Condition Guide

Report ID: 26,560,992

Version:

27 Feb 2025

Make: Model: Subaru Impreza **Body Style:** Hatchback

2013

Registration:

Created:

Year:

Reg Expiry:

26560992


WoF Expiry: 17 Feb 2026 VIN:

Odometer: 72,650 Kms 7AT0GF09X25015263 Next Service: 82,648 kms

Good No: Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Note: some defects & blemishes may not be displayed in the diagram **Body Inspection Comments**

Conditions During Body Inspection:

Dry

Under Carriage & Under Bonnet Inspection Comments

Fwd

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

18 Feb 2025 Marlon Espena Inspected by: Date:

Name:

| | Pass | Fail | N/A | |
|------------------------------|--------------|---------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\times \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | <i>V V</i> | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | |
| Left front | 6 | .0 | mm | |
| Right front | 6.0 | | mm | |
| Left rear | 7.0 | | mm | |
| Right rear | 7.0 | | mm | |
| Spare | | N/A | | |
| Suspension | | | | |
| Suspension performance | V V | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | \(\times \) | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | / | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | \(\times \) | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |
| | | | | |

Signature: