

Basic Vehicle Condition Guide

Report ID: 26,578,592

3 Version:

10 Mar 2025 Created:

Make: Model: Toyota Aqua **Body Style:** Hatchback

Year: 2015

WoF Expiry:

Registration: **Odometer:**

Reg Expiry:

Good No: 26578592

07 Mar 2026 VIN: 7AT0H65YX25428619 **Next Service:**


75,758

Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

65,765 Kms



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

10 Mar 2025 Lewis Dolamore Inspected by: Date:

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
~		
~		
d depth	of tyre	es)
7	.0	mm
7.0		mm
7.0		mm
7.0		mm
	Yes	
~		
~		
V		
~		
<i>'</i>		
V		
<i>v</i>		
~		
~		
\(\times \)		
\(\times \)		
~		
\(\times \) \(\t		
\(\times \) \(\t		
\(\times \) \(\t		
V V V V V V		
V V V V V		
V V V V V		
V V V V V		
V V V V V V		
V V V V V V		
V V V V V V		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

Signature: