

Report ID: 26,578,657 1 Version: 08 Apr 2025 Created:

Make:	Toyota	Model:	Corolla	Body Style:	Wagon		Pass	Fail	N/A
Year:	2014	Registration:		Reg Expiry:		Engine	1	l	L
WoF Expiry:	04 Apr 2026	Odometer:	75,860 Kms	Good No:	26578657	Oil level	~		
VIN:	7AT0H607X25044867	Next Service:	85,849 Kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a run mechan	lical inspection prior to	purchase and t	lis can be arranged to	or an additional of	.narge.	Coolant condition	~		
			SC		Р	Performance	~		
<b>Key:</b> S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust				10	EL SUPISC	Operation	~		
PT = paint defe	ect NP	1				Noise	<		
C = crack						Clutch			~
P = pin dent	PT de				~HHL	CV joints	<		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
		$\sim$	SC			Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	4.	.5	mm
						Right front	4.5		mm
						Left rear	5.5		mm
Conditions During Body Inspection: Dry						Right rear	5.5 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock abso							~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		ļ
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Average S	iteering wheel p	eelina			Wipers (front & rear)	~		
	, it enage, o					Window winder FL	~		
General	<u>Comments</u>					Window winder FR	~		
	<u>connents</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only) Number of keys			~
							2		<u> </u>
Road Conditions During Test Drive:   Dry       Central locking     Remote locking							~		
Engine Timing Mechanism: Timing Chain Remote locking							~		
Suidence of Cam Balt Deple comparts - N. ( A. 1994 - King)									<b>v</b>
Evidence of Cam Beit Replacement: Not Applicable Kms: Reversing camera									~
Inspected by: Caleb Spicer Lee Date: 08 Apr 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....